ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0023, W0025, W0008, W0006, W0021, W0301, W0307, W

Street Name
NA, 8th Crs, Bimel Behind Rd

Significant Landmark
Balaji Layout near Singapura Main Road

Segment No.
11/C-W0023/S083314

Total Length (m)
479.44

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	40.20	77.535200	13.078287	77.535114	13.077934	W0196	DEAD END
2	45.88	77.535390	13.078355	77.535506	13.078754	W0196	DEAD END
3	46.30	77.535137	13.078436	77.535267	13.078835	W0196	DEAD END
4	43.08	77.534944	13.078391	77.534841	13.078015	W0196	DEAD END
5	58.82	77.536615	13.081636	77.536605	13.081104	W0008	DEAD END
6	72.44	77.536924	13.081646	77.536917	13.080991	W0008	DEAD END
7	81.05	77.537217	13.081633	77.537214	13.080900	W0008	DEAD END
8	91.67	77.536658	13.081684	77.537503	13.081681	W0021	W0027

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads at Balaji Layout near Singapura Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zon

Sanctioned Estimated Amount (Rs.)
2400000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to roads at Balaji Layout near Singapura Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-15-000025

Work Order No.
EE/BTP/BBMP/E-PMT/353/2014-15

Work Order Date
24/03/2015

Period of Extention
60 DAYS

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #

28/03/2015	23/03/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N.THIRUNAGENDRA		0.00
Phone No.	**E-Mail ID**	
9845547072		

Field Inspection Details

Number of Trees	Any Other Information	Name
10		SURESH
Date of Inspection	**Remarks**	
27/11/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0023, W0025, W0008, W0006, W0021, W

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/11/2016	27/12/2016	COMPLETED
SE	VASU K M	27/11/2016	27/12/2016	COMPLETED
EE	YARAPPA REDDY	27/11/2016	27/12/2016	COMPLETED
AEE	SHIVAKUMAR	27/11/2016	27/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0023, W0025, W0008, W0006,

AE	SURESH	27/11/2016	27/12/2016	COMPLETED
AE	SURESH	27/11/2016	27/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0023, W0025, W0008, W0006,